ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
10

Ward Name
Dodda Bommasandra

Street ID
W0235, W0239, W0233, W0225, W0227, W0247, W0231, W

Street Name
NA, 4th Crs

Significant Landmark
Raghavendra mata at venkatagiriyappa layout

Segment No.
10/C-W0235/S042904

Total Length (m)
170.63

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	33.29	77.557118	13.063493	77.557114	13.063192	DEAD END	W0160
2	137.34	77.555933	13.062165	77.557200	13.062159	W0247	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work
Construction of RCC Drain and covering slab near Raghavendra mata at venkatagiriyappa layout in ward no 10 (Doddabommasandra) Vidyaranayapura Sub-D

Sanctioned Estimated Amount (Rs.)
1400000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Drain Maintenance

Other Work Type

Tender
Tender

Work Details
Construction of RCC Drain and covering slab near Raghavendra mata at venkatagiriyappa layout in ward no 10 (Doddabommasandra) Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
010-16-000019

Work Order No.
EE/BTP/BBMP/E-PMT/301/2015-16

Work Order Date
24/03/2016

Period of Extention
90 DAYS

Defect Liability Period From
23/03/2016

Defect Liability Period To
22/03/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
M N SHIVAKUMAR

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

hone No.	E-Mail ID
9448956136	

Field Inspection Details

Number of Trees	Any Other Information	Name
6		MADHAVA RAO
Date of Inspection	**Remarks**	
27/06/2016	completed	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0235, W0239, W0233, W0225,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	27/06/2016	27/07/2016	COMPLETED
SE	VASU K M	27/06/2016	27/07/2016	COMPLETED
EE	YARAPPA REDDY	27/06/2016	27/07/2016	COMPLETED
AEE	SHIVAKUMAR	27/06/2016	27/07/2016	COMPLETED
AE	MADHAVA RAO	27/06/2016	27/07/2016	COMPLETED
AE	MADHAVA RAO	27/06/2016	27/07/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0235, W0239, W0233, W0225,